

Location	Manufacturer	Model	Serial	Cost to replace Evap Coil / Combust box
ADMIN	CARRIER - CHILLER	30GTN040-520KA	3302F73580	43,639. /
	PEERLESS	210-4-WVP	210 10464	/ 19,369
	TACO	PUMP	1641	No heat exchanger or coil
	TACO	PUMP	1641	No heat exchanger or coil
	BOHN	AIR HANDLER	AC390W-S	6,046
	BOHN	AIR HANDLER	AC390W-S	6,046
	BOHN	AIR HANDLER	AC390W-S	6,046
	BOHN	AIR HANDLER	AC390W-S	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	INTERNATIONAL	FAN COIL	8CP425-2	6,046
	CENTRI MASTER	EXHAUST		No heat exchanger or coil
COMM. CENTER	CARRIER	48D5008510	2890G93031	5555 / 6596
	CARRIER	48D5008510	2980G93026	5555 / 6596
	CARRIER	48D5008510	2890G93028	5555 / 6596
	CARRIER	38CK048300	2598E20601	2990
	CARRIER	58PAV090-18	3298A11130	1884
	LIEBERT	HME036EP1		4337
	LIEBERT	HME036EP1		4337
	LENNOX	HS10411U-5A	5178E20941	2837
	HAYES	105VF9-0F	23792	1884
	MARV AIR/COMPAC II	AVP60AD0SC-1000	CK7404	4337
	MARV AIR/COMPAC II	AVP60AD0SC-1000	CK7410	4337
STA 1	CARRIER	4855-048080341AA	5097G10221	2990 / 1884
	CARRIER	4855-048080341AA	5097G10222	2990 / 1884
STA 2	CARRIER	58DHC095-CC	1090A09393	1884
	CARRIER	28EH060530DL	0788E28334	2990
	BRYANT	561CP060-G	240IEI0309	2990
STA 3	CARRIER	38CKBO24320	296E13824	2990
	CARRIER	38CKB04250	4296E11395	2990
	CARRIER	38CKB060500	1496E8982	2990
	CARRIER	58WAV045-08	2196A05807	1884
	CARRIER	58WAV091-16	1096A02601	1884
	CARRIER	58WAV111-20	3596A05290	1884
STA 4	RHEEM	RKKA-A048JK08X	2A5638A0AAF01001010	2990
STA 5	YORK	D3CG060N8225D	NHYM049892	2990
	GREENHECK	28504	CE7.5	No heat exchanger or coil
	GREENHECK	28504	CE7.5	No heat exchanger or coil
BC TRAILER	BARD	36WA4	55K6128296	2990
STA 6	CARRIER	58SSB095-BC	5187C20121	1884
	CARRIER	38TH060300	1290E184488	2990
	CARRIER	COIL	28RC075-000	2990
	DAY&NITE	5091A13388	395CAV03675ADJA	1884
STA 7	DAY&NITE	395CAV060090	2889A14495	1884

Location	Manufacturer	Model	Serial	Cost to replace Evap Coil / Combust box	
	DAY&NITE	395CAV048075	3589A15522		1884
	DAY&NITE	39CAVO36055	4789A10877		1884
	DAY&NITE		Aug-89 RT-36-ACW-W		2990
	DAY&NITE		Jul-89 RT-36-ACW-W		2990
	DAY&NITE		Sep-89 RT-24-ACW-W		2990
	DAY&NITE	591ANX036000AAAA	3789E10541		2990
	DAY&NITE	591ANX042000ABAA	39895-48-591		2990
	DAY&NITE	591ANX024000AAAA	3089E71944		2990
STA 8	LENNOX	XC1303623002	5807D02022		2990
	LENNOX	CX3442B6F1	6007CD2781		2990
STA 9	DAY&NITE	2188E32174	C288A19611		2990
	DAY&NITE	COIL	519DXX06000MAA		1884
	DAY&NITE	56EJX06000AGAA	2188E32174		2990
STA 10	CARRIER	48SS048100551AA	2797G10112	2990	/ 1884
	CARRIER	48SS048100551AA	2797G10111	2990	/ 1884
SUPPLY	REZNOR	FURN	NO PLATE		1884
TRAINING	CARRIER	4865-036090301	0500G10514	2990	/ 1884
	DAY&NITE	5B4AN036080AC	0592C30438	2990	/ 1884
	CARRIER	4865-036090301	0500G10515	2990	/ 1884
	3 UNITS	BLEACHED OUT	PAINTED OUT	2990	/ 1884
	CARRIER	48GS036090501	0600G10506	2990	/ 1884
	CARRIER	48GS036090501	3899G10615	2990	/ 1884
	BRYANT	588AMW036080NBAF	0805G5B60	2990	/ 1884
	DAY&NITE		BLEACHED OUT	2990	/ 1884
	mitsubishi electric	PU12EK 1	29D01860D		2990
APPARATUS SHOP	JANITROL		681560 177799675		1884
	JANITROL		681560 77799683		1884
	JANITROL	NO PLATE			1884
	JANITROL	NO PLATE			1884
	JANITROL	NO PLATE			1884
	JANITROL	NO PLATE			1884
HOSE TOWER	HAYES		27259 200-350-CF		1184
	FRASER JOHNSTON	NO PLATE		2990	/ 1884
STA 11	YORK	H4DE048525A	(S)EFJM332749		2257
	YORK	H4DB060525A	(S)EKJM453232		2257
	YORK	P3URC20N09501D	EKHJM419095		1884
	YORK	F3URC16NO7501D	(S)EKJM454360		1884
	YORK	H4DB024506A	(S)EKJM447837		2257
	YORK	P3DHA08N03701B	(S)EKJM440379		1884
STA 12	DAY&NITE	58DPV060115AAAA	174G20391		2257
STA 13	BRYANT	588ANWO48100AFAG	3597G10180	2990	/ 1884
STA 14	CARRIER	48GS-048115301	3799G10057	2990	/ 1884
	CARRIER	48GS-048115301	3799G10060	2990	/ 1884
STA 15	CARRIER		48KLA036-500CE	2990	/ 1884

Location	Manufacturer	Model	Serial	Cost to replace Evap Coil / Combust box
	CARRIER		48KHA042-521CF	2990 / 1884
STA16	COLEMAN	7956C856	49275087	1884
	CARRIER	38CK042300	2092E24014	2990
STA 17	TRANE	TDE120A960ML	234J8T1G	1884
	TRANE	2TTB0060A100AA	22318253F	2990
STA 22	CARRIER	38CKC042510	0799E20063	2990
	CARRIER	38CKC060520	4999E06369	2990
	CARRIER	38CKC030330	4599E15986	2990
	CARRIER	58WAV091-16	3099A08331	1884
	CARRIER	58WAV111-20	4299A08952	1884
	CARRIER	58WAV045-08	3799A07086	1884
STA 69	PAYNE	PA10J060-C	100E04286	1884
	DAY&NITE	373LAV060135	4295A17716	1884
	BRYANT	582ANW036060AAAF	2500G10614	2990 / 1884
STA 70	YORK	DIGA030N03206B	NMAN1169016	2990 / 1884
	YORK	DIGA030N03206B	NMAN169809	2990 / 1884
STA 81	RHEEM	RKKA-A060JK10E	1X5642ADAAAF339615845	2990
	RHEEM	BLEACHED OUT		2990
STA 82	YORK	H5DB048525A	WFLM052100	2990
	YORK	H4DB048525A	WKMMOOO138	2990
	YORK	H4DB024506A	WLLM024673	2990
	YORK	P3URC16N07501E	WLLMO10694	1884
	YORK	P3URC20N09501E	WLLMO23255	1884
	YORK	P3DHA10N03701D	WNKMOO4565	1884
STA 83	BRYANT	582ANW036060AAAF	1002611428	2990 / 1884
	CARRIER	2807E27906	2525HBR318A330	1884
	CARRIER	3508E15059	24ABB342A300	1884
	CARRIER	58MXB080-16	1508A00951	1884
STA 84	DAY&NITE	56BJ042	5286A11869	2990
	DAY&NITE	565B042	5288411872	2990
	DAY&NITE	565BJ036-A	1097A15605	2990
STA 85	COLEMAN	7655-856	88287488	1884
	INTERTHEM	CNS42B	A000708911	1884
STA 86	CARRIER	58SSC110-LC	1191A07368	1884
	TRANE	TTB048C100A	N305501BF	2990
STA 87	YORK	H4DB048525A	EMHM836499	2990
	YORK	P3URC16N07501C	EFHM653070	1884
	YORK	H4DB048525A	ELHM836822	2990
	YORK	P3URD20N0951C	EMHM863845	1884
FIRE INVEST.	YORK	H2DB024506B	EHGM302746	2990
	YORK	P3DHA08N03701A	EFHM638359	1884
STA 88	CARRIER	58WAV091-14	3095A15037	1884
	CARRIER	38CKB0605N	1195E16464	2990
	CARRIER	58WAV111-20	1595A19488	1884
	CARRIER	38CKB042500	3895E10362	2990
FPB EAST	COLEMAN	797SH856	108869694	1884
	CARRIER	38TH042310	0689E17812	2990
Manufacturer, model, and serial number are believed to be accurate but are not guaranteed. Contractor is to confirm the accuracy of the information and advise the Fire District in writing of any discrepancies within 90 days of award.				