To: Contra Costa County Housing Authority Board of Commissioners

From: Joseph Villarreal, Housing Authority

Date: September 14, 2021



Contra Costa County

Subject: CONTRACT WITH DIABLO BOILER FOR HACIENDA EMERGENCY BOILER REPLACEMENT

RECOMMENDATIONS

RATIFY the Housing Authority Executive Director's execution of a contract with Diablo Boiler in an amount not to exceed \$158,624 to replace the boiler system at the Hacienda Development located at 1111 Ferry Street, Martinez, for the period August 17 through December 2, 2021.

BACKGROUND

Between July 29 – August 1, 2021, the two boilers at the Hacienda Development in Martinez malfunctioned. The contractor who attempted to fix the boilers informed staff that the necessary parts to repair the boilers were no longer available because the company (Webben-Jarco) went out of business. The boilers needed to be replaced immediately. Staff identified the boilers as an emergency repair item.

Diablo Boiler can perform the emergency work. They will remove old boilers and replace them with a new updated boiler system. The total amount for their services will not exceed \$158,624.

Action of	Board On: 09/14/2021	✓ APPROVED AS RECOMMENDED ☐ OTHER
Clerks Notes:		
VOTE OF COMMISSIONERS		
AYE:	John Gioia, Commissioner	
	Candace Andersen, Commissioner	
	Diane Burgis, Commissioner	I hereby certify that this is a true and correct copy of an action taken and entered on the minutes of the Board of Supervisors on the date shown.
	Karen Mitchoff, Commissioner	ATTESTED: September 14, 2021 Joseph Villarreal, Executive Director
	Federal D. Glover, Commissioner	
	Cynthia Jordan, Commissioner	By: June McHuen, Deputy
ABSENT:	Joanne Segura, Commissioner	

Contact: 925-957-8028

FISCAL IMPACT

Funding for this contract is included in HACCC's current budget using the public housing capital funding provided by the U.S. Department of Housing and Urban Development.

CONSEQUENCE OF NEGATIVE ACTION

If the Board of Commissioners does not approve this contract, the boilers will not be repaired and will continue to malfunction and/or stop working.