



**Contra
Costa
County**

To: Board of Supervisors
From: Brian M. Balbas, Public Works Director/Chief Engineer
Date: August 10, 2021

Subject: Approve and Authorize to fully close a portion of Pinehurst Road, between August 16, 2021 and October 31, 2021, Canyon area.

RECOMMENDATION(S):

ADOPT Resolution No. 2021/245 approving and authorizing the Public Works Director, or designee, to fully close a portion of Pinehurst Road between Canyon Road and Skyline Boulevard, except for emergency vehicles and local traffic, for a maximum of 26 consecutive calendar days between August 16, 2021 and October 31, 2021, 24 hours per day, for the purpose of the Pinehurst Road Sinkhole and Culvert Repair Project, County Project No. 0672-6U6202, Federal Project No. ER 32LO(517), Canyon area. (District II)

FISCAL IMPACT:

No fiscal impact.

BACKGROUND:

To enable the contractor to replace a damaged Corrugated Metal Pipe (CMP) with a Reinforced Concrete Pipe (RCP) and repairing the CMP using invert paving to restore Pinehurst Road in the most efficient and least impactful way to the local community.

☒ APPROVE

☐ OTHER

☒ RECOMMENDATION OF CNTY ADMINISTRATOR

☐ RECOMMENDATION OF BOARD COMMITTEE

Action of Board On: **08/10/2021** ☒ APPROVED AS RECOMMENDED ☐ OTHER

Clerks Notes:

VOTE OF SUPERVISORS

AYE: John Gioia, District I Supervisor
Candace Andersen, District II Supervisor
Diane Burgis, District III Supervisor
Karen Mitchoff, District IV Supervisor
Federal D. Glover, District V Supervisor

I hereby certify that this is a true and correct copy of an action taken and entered on the minutes of the Board of Supervisors on the date shown.

ATTESTED: August 10, 2021

Monica Nino, County Administrator and Clerk of the Board of Supervisors

By: Stacey M. Boyd, Deputy

Contact: Bob Hendry (925)
374-2136

CONSEQUENCE OF NEGATIVE ACTION:

Contractor will be unable to close the road for planned activities. Pinehurst Road Sinkhole and Culvert Repair, County Project No. 0672-6U6202, Federal Project No. ER 32LO(517) will be delayed and may not be able to be constructed.

ATTACHMENTS

Resolution No. 2021/245